



Magnetic Shielding is normally for:

1. Mains High Tension Cables
2. Transformer Sub Station
3. Rotating machinery (large electric motors)

The principle of shielding magnetic fields is 'magnetic reluctance', this is achieved by welding steel barriers made from special low carbon steels or non-grain oriented electrical steels.